





ACCU30xxx Outdoor Unit

Guide for Unpacking, Receiving, and Moving



Eyebolts must be rated for angular lifting with a shoulder similar to the one shown.

- Minimum weight rating (90° lift)
 - 726 kg (1600 lb)
- Suggested McMaster Carr part number
 - 3040T14



Worldwide Customer Support

Contact www.schneiderelectric.com/support for more information.

© 2014–2025 Schneider Electric is a trademark of Schneider Electric Industries S.A.S., or its affiliated companies. All other trademarks are property of their respective owners.

990-91200A-001

11/2025

English

Before proceeding, download the installation manual from the website, www.schneiderelectric.com, by entering the first six characters of the model number in the search box and selecting the product page. The manual can be found in the documentation section. The manual includes important warnings, loading specifications, and grounding instructions.

Recyclable materials: The shipping materials are recyclable. Save them for later use, or dispose of them appropriately.

Note: When possible, leave the equipment on the pallet until you are ready to move it to its final location.

Receiving

Inspect the exterior packaging. Before unpacking the shipment, verify that the labeled container matches the bill of lading.

Inspect the equipment. Once you have unpacked the equipment, carefully inspect its exterior.

Note: In case of shipping damage such as scratches or dents contact Schneider Electric. See Worldwide Customer Support for contact information.